

Report for:

Cynthia Berg South Coast Air Quality Management District 21865 Copley Drive Diamond Bar, CA 91765

Eurofins Built Environment Testing West, LLC

Regarding: Project: 2025 LA Wildfires / Eaton Shepard Church; Eaton Shepard Church

EML ID: 3996519

Approved by:

Dates of Analysis:

Asbestos TEM - AHERA (40CFR Part 763, Subpart E, Appendix

A): 03-24-2025

Approved Signatory
Arthur Bucio

Service SOPs: Asbestos TEM - AHERA (40CFR Part 763, Subpart E, Appendix A) (EM-AS-S-8578) NVLAP Lab Code 200757-0

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. Due to the nature of the analyses performed, field blank correction of results is not applied. The results relate only to the samples as received and tested.

Eurofins Built Environment Testing West, LLC ("the Company"), a member of the Eurofins Built Environment Testing group of companies, shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

Eurofins Built Environment Testing West, LLC

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (833) 465-5857 www.eurofinsus.com/Built

EMLab ID: 3996519, Page 2 of 4

Client: South Coast Air Quality Management District

C/O: Cynthia Berg

Re: 2025 LA Wildfires / Eaton Shepard Church;

Eaton Shepard Church

Date of Sampling: 03-20-2025 Date of Receipt: 03-21-2025 Date of Report: 03-24-2025

ASBESTOS TEM AHERA REPORT

Lab ID-Version‡ Location Analysis Date	Volume (liters)	Area Analyzed (mm2)	Grid Openings Examined	Analytical Sensitivity (S/cm3)		Asbestos Types	Asbestos Structures (S)		§Asbestos Concentration	
Allalysis Date		(/					>= 5µm	>=0.5-<5µm	S/mm2	S/cm3
19891732-1	7130	0.04	4	0.001	0	No Structures Detected	0	0	<24.752	< 0.001
D1648689 Asbestos										
Sampling										
03/24/2025										
Comments:	•		•	•	•					

§ Asbestos Concentration has been rounded to three significant figures to reflect analytical precision.

The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government.

Digital images of diffraction patterns and copies of analytical bench sheets pertaining to this project are available upon request. The estimated measurement of uncertainty and 95% confidence interval for the test results are also available upon request.

The laboratory is not responsible for data collected by personnel who are not part of the laboratory. Results reported in both structures/cm3 and structures/mm2 are dependent on the volume of air sampled and measured by non-laboratory personnel.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins Built Environment Testing West, LLC

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (833) 465-5857 www.eurofinsus.com/Built

Lab ID-Version‡: 19890812-0

EMLab ID: 3996519, Page 3 of 4

Client: South Coast Air Quality Management District

C/O: Cynthia Berg

Re: 2025 LA Wildfires / Eaton Shepard Church;

Eaton Shepard Church

Date of Sampling: 03-20-2025 Date of Receipt: 03-21-2025 Date of Report: 03-24-2025

ASBESTOS TEM AHERA REPORT

Total Samples Submitted: 2
Total Samples Analyzed: 1
Total Samples Not Analyzed: 1

D1648689, Asbestos Sampling

NOT ANALYZED NO SAMPLE SUBMITTED

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Sample results described as "Positive Stop" were not analyzed because the previous sample layer(s) contained asbestos >1%. Sample results described as "Sample Bag Empty" were not analyzed because while the sample bag was submitted it did not contain a discernible sample. Sample results described as "No Sample Submitted" were not analyzed because the sample bag was not submitted with the project. Sample results described as "Insufficient Sample" were not analyzed because while the sample was submitted for analysis, there was insufficient material present to analyze the sample confidently. Sample results described as "Per Client Request" were submitted to the laboratory but not analyzed because the laboratory was requested to hold the sample.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins Built Environment Testing West, LLC

Eurofins Built Environment Testing West, LLC

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (833) 465-5857 www.eurofinsus.com/Built

Client: South Coast Air Quality Management District

C/O: Cynthia Berg

Re: 2025 LA Wildfires / Eaton Shepard Church;

Eaton Shepard Church

Date of Sampling: 03-20-2025 Date of Receipt: 03-21-2025 Date of Report: 03-24-2025

ASBESTOS TEM AHERA REPORT

PROJECT ANALYST AND SIGNATORY REPORT

Project Analyst

Analyst: Arthur Bucio

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

[‡] A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".



CHAIN OF CUSTODY 💸 eurofins WEATHER Fog Rain Snow Wind Clear REQUESTED SERVICES None www.eurofinsus.com/Built **Built Environment Testing** Non-Culturable Culturable Light Moderate Marlton, NJ: 3000 Lincoln Dr E, Ste. A, Marlton, NJ 08053 * (866) 871-1984 BioCassette[™] Andersen, SAS Other Requests Spore Tape, Phoenix, AZ: 1501 West Knudsen Drive, Phoenix, AZ 85027 * (800) 651-4802 Swab, Water, Bulk, Dust, Soil Trap Swab, Bulk Contact Plate Burlingame, CA: 111 Anza Blvd, Suite 122, Burlingame, CA 94010 * (866) 888-6653 CONTACT INFORMATION South Coast Air Quality Management District (42519) 21865 Copley Drive Diamond Bar, CA 91765 Company Cynthia Berg Contact: Special Instructions: 909-396-2181 Phone: TURN AROUND TIME CODES - (TAT) PROJECT INFORMATION est STD - Standard (Default) 2025 LA Wildfires Rushes received after 2pm Project ID: or on weekends, will be (please specify Project Eaton Shepherd Church ND - Next Business Day Description: considered received the Sampling Project next business day. Please 2/20/15 0000 91001 SD - Same Business Day Zip Code Date/Time: alert us in advance of Sampled Ebenulin WH - Weekend/Holiday/ASAP 2025000028 weekend analysis needs. PO Number TEM-Sample Total TAT NOTES SAMPLE ID DESCRIPTION Volume/Area Type AHERA (Above) (Time of day, Temp, RH, etc.) (Below) (as applicable) 01448689 ND ect= 7.20 m Play 5 5.00 1pm stop tire: 3/2/1/25 000 DATE & TIME RECEIVED BY DATE & TIME SAMPLE TYPE CODES RELINQUISHED BY 3921/25 CP - Contact Plate | T - Tape O - Other: BC - BioCassette " Alijah Navelta 03/21/25 J. Ebenner 1257 A1S - Andersen ST - Spore Trap SW - Swab SO - Soil SAS - Surface Air Sampler B - Bulk P - Potable Water D - Dust NP - Non-potable Water